## MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)  R. 12/3/82, R. 6/8/83						
	Section I	ion1 D432112 7		Typ	TYPE III	
MANUFACTURERS NAME U. S. Paint, Division of Grow Group, Inc.						
STREET ADDRESS. 831 S. 21st Street CITY.STATE.AND ZIPCODE St. Louis, Missouri 63103						
CATALYST FOR USE WITH  INFORMATION TELEPHONE NO. (314) 621-0525  PRODUCT CLASS Polyisocyanate Resin  CATALYST FOR USE WITH  TYPEI, CLASSES I, II + III  MANUFACTURERS CODE IDENTIFICATION G3010 (92-C-39)						
TRADE NAME AWL-CAT #2 Topcoat Converter for Spray Application						
Section II — HAZARDOUS INGREDIENTS						
INGREDIENT	Volume PERCENT	TLV PPM mg/M³		LEL	VAPOR PRESSURE in mm Hg	
	24 11 . 4 25 36  PHYSICA  VAPOR DE  PERCENT VOLATION BY VOLUME	NSITY X	1440 375 435 540 N.E. HEAVIER.	2.2 1.27 1.1 1.7	20° C 76.0 38.0 9.5 1.2 <0.10	
Section IV — FIRE AND EXPLOSION HAZARD DATA						
Flammable Liquid 20°-100°F X  EXTINGUISHNG MEDIA  Dry Chemical or Foam					LEL 1.1	
UNUSUAL FIRE AND EXPLOSION HAZARDS Do not expose to spark or open flame  SPECIAL FIRE FIGHTING PROCEDURES - Personnel who are fighting isocyanate fires should wear self-contained breathing apparatus.						

Section V — HEALTH HAZARD DATA				
THRESHOLD LIMIT VALUE 100 to 400 PPM				
EFFECTS OF OVEREXPOSURE Eye and upper respiratory irritant				
ACUTE				
CHRONIC				
EMERGENCY AND FIRST AID PROCEDURES If exposed to excess vapor, remove to fresh air and seek medical attention. If splashed on skin wash with soap and water and seek immediate medical attention. If swallowed CALL A PHYSICIAN IMMEDIATELY. DO NOT induce vomiting.				
Section VI — REACTIVITY DATA				
France best on original materials				
STABILITY UNSTABLE X STABLE CONDITIONS TO AVOID - Excess heat or oxidizing materials.  INCOMPATABILITY (Materials to avoid) - AVOID contact with water, alcohol, amines, and other compounds which react with isocyanates.  HAZARDOUS DECOMPOSITION PRODUCTS				
HAZARDOUS POLYMERIZATION MAY OCCUR X WILL NOT OCCUR CONDITIONS TO AVOID				
Section VII — SPILL OR LEAK PROCEDURES				
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Affected area should be treated with an absorbing				
compound and then material placed in a tightly closed container.				
WASTE DISPOSAL METHOD In accordance with local, state, and federal environmental control regulations				
Section VIII — SPECIAL PROTECTION INFORMATION				
RESPIRATORY PROTECTION NIOSH/MSHA approved combination vapor/particulate or air supplied respirator.				
VENTILATION Sufficient to keep air supply above threshold limit values.				
PROTECTIVE GLOVES Rubber or Plastic				
EYE PROTECTION Goggles				
OTHER PROTECTIVE EQUIPMENT Hypersensitive persons should use a protective cream.				
Section IX — SPECIAL PRECAUTIONS				
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Keep away from excess heat, sparks and flames.				
DOL STORAGE CATEGORY				
OTHER PRECAUTIONS				
FOR PROFESSIONAL USE ONLY				